

1/12




FIG. 1

10064105 "06.1.02

2/12

32

SERIAL 12726		ENGINE		JOB NUMBER 000000-020		PAGE 10	
MODEL P4400		CUSTOMER		NOTES/REMARKS		11. ITEMIZATION OR MARK UNDER INSPECTION	
PART NUMBER		QTY		NO RECORD OF FITS & CLEARANCES ARE REQUIRED TO COMPLETE THIS SECTION			
506367-01	SET	1AW ASSY (SERVING-79-43) (EN 72-41-72)	723141	0760	0001	1	33242
506380-01	SET	SERVING-79-56	4RECORD SER NUMBER	0760			
516033-01	SET	SERVING-79-65	4RECORD SER NUMBER	0760			
21670511104							
REPAIR 506315-01 TO 506367-01 PER SERVING-79-43							
INSPECT AND ZIELD PER PARA 28 OF SERVING-79-47							
FIELD 506367-01 TO 506380-01 PER SERVING-79-56							
REPAIR 506380-01 TO 516033-01 PER SERVING-79-65							

34

FIG. 2

10064105 " 06.1.02

3/12




FIG. 3

10064105-06.102

4/12

TEARDOWN

SALES ORDER #

765432

SECTION

78-33-00

PUTTED

ABC AIRLINES

204

ENGINE FAN CASE

206

78-33-00-2

CASE & VALVE ASSY-FAN EXIT

0078-33-00-2-1

CASE & VALVE ASSY-FAN EXIT

00078-33-00-2-10

WIDGET

212

12345

12345-01 (EXPECTED)

12346 (PLANNED)

12350

OK

210

208

202

FIG. 4

10064105 . 05.1.02

5/12




FIG 5

10064105-05102

6/12

402

404

400

INSPECTION

SALES ORDER # 987654 ▾ SECTION 72-52-00 ▾
P4074 XYZ AIRLINES HPT C/D & FINAL ASSY

PART # 506745-01 ▾ QTY 1 ▾

CASE-TURB, ASSY OF

TECH INFO CONFIGURATION DISPOSITION STATUS

☒ EM
☐ IPC
☐ SB
☐ SPM

VIEW

406

408

FIG. 6a

10064105 . 06.1.02

402

INSPECTION

SALES ORDER # 987654 ▼
RW4074
XJT AIRLINES
PART # 50L745-01 ▼

SECTION 72-52-00 ▼
HPT QD & FINAL ASSY
QTY 1 ▼

TECH INFO

CONFIGURATION

DISPOSITION

STATUS

416 SLID 725200-02-040

418 REQUIRED MODS

RW46-11272-141
RW46-11272-159

410 EXECUTIVE REPLACEMENTS

QTY	TYPE	REASON
53L010-01	1	R REPLACE
53L020	1	R REPLACE

420

FIG. 6b

10064105 . 06.1.02

4082

INSPECTION

SALES ORDER # SECTION
 P44074 HRT C/D & FINAL ASSY
 XYZ AIRLINES

PART # QTY

TECH INFO	CONFIGURATION	DISPOSITION	STATUS
<input checked="" type="radio"/> SERVICEABLE <input type="radio"/> REMOVE FROM SERVICE <input type="radio"/> INTERNAL REPAIR <input type="radio"/> CHANGE INTERNAL REPAIR <input type="radio"/> EXTERNAL REPAIR <input type="radio"/> HOLD			
Disposition			

412

FIG. 6c

8/12

10064105 - 06.1.02

9/12

402

INSPECTION

SALES ORDER # 987654 SECTION 32-52-001
HPT CID # FINAL ASSY

PART # QTY

TECH INFO

CONFIGURATION

DISPOSITION

STATUS

LID	PART #	DESCR	STATUS
73500-01-001	534071	PORR & ST. ASSY	○ ○ ○
74500-01-160	504976	SEAL	● ○ ○
74500-01-170	501965	METERING PLUG	○ ● ○
74500-01-001	504977	PLATE	○ ○ ●
74500-02-410	53401001	CASE-TUBES ASSY	○ ○ ●
74500-02-040	504978	GRAVELT	● ○ ○
74500-02-160	534013	GRAVELT	● ○ ○
74500-02-180	504969	SEAL	○ ○ ●


414

422

FIG. 6d

10064105 . 06.1.02

10/12

PART # 12345-01
NAME B WIDGET
CUST ABC AIRLINES
306 { SERVICEABLE
 310
ROUTE = KITTING, ASSY

300 ↗



FIG 7a

10064105-06102

11/12

PART # 12345-01
NAME 8 WIDGET
COST 8 ABC AIRLINES
306 { REMOVE FROM SVC
[Barcode]
ROUTE 8 MRB } 310

300 ↗

FIG. 7b

10064105-06102

12/12

PART # 12345-01
NAME WIDGET
COST ABC AIRLINES
306 {REPAIR
310
ROUTE XYZ VENDOR

300 ↗

FIG. 7c

10064105-001102